

Work Order ID 112983

Tuesday, February 11, 2014 11:31:59 AM

112983

Page 1

Item ID: PB67-43001-47

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Base Assembly

Start Date: 2/11/2014 Start Qty: 6.00 ***6***

Cust Item ID:

Required Date: 2/28/2014 Req'd Qty: 6.00 ***6***

Customer:

Reference:

Approvals: Process Plan: AMF Date: 14-2-11

Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____

SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID

Tool #

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

Draw Nbr

Revision Nbr

B67-43001-47

Rev C

100

100

Large Fab

Large Fab

Large Fab

Memo

1- weld as per dwg B67-43001 using jig

0.00

DAS
24
9-89

QC 14.3.24

0.00

DAS
43
9-89

6*

14-03-24

110

110

QC

Quality Control

QC5- Inspect part completeness to step on W/O

Memo

0.00

0.00

DAS
43
9-89

6x

14-03-24

120

120

QC

Quality Control

QC9- Inspect visual per QSI004- Fusion Welds

Memo

0.00

0.00

DAS
43
9-89

6

14-03-24

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

DQA: _____ Date: _____

QA Closed: _____ Date: _____

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Work Order Update ☐	AGAINST DEPARTMENT/PROCESS <table style="width: 100%;"> <tr> <td>Skid-tube ☐</td> <td>Crosstube ☐</td> <td>Water Jet ☐</td> <td>Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>	Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐															
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐															
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐															
Large Fab ☐	Composite ☐	Supplier ☐																

Root Cause	Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Doc/Data									
Equip/Tooling									
Operator									
Material									
Setup									
Other									
Process									
Supplier									
Training									
Unapproved									

FAULT CATEGORY

Landing Gear	General	Other
☐ Bending	☐ Bend	☐ Grain
☐ Centre Not Concentric to O/S	☐ BOM/Route	☐ Hardware
☐ Cracks	☐ Broken/Damaged	☐ Inspection Incomplete
☐ Crushed/Crimped	☐ Burrs	☐ Instructions Incomplete/Unclear
☐ Cuffs	☐ Contamination	☐ Maintenance
☐ Heat Treat	☐ Countersink	☐ Mislabeled
☐ Inspection Strip in Tube	☐ Cut Too Short	☐ Misread
☐ Ripples in Bend	☐ Drill Holes	☐ Offset
☐ Torque Waves in Extrusion	☐ Drawing	☐ Out of Calibration
☐ Turning Sequence	☐ Finish	☐ Out of Sequence
☐ Wave/Twist in Tube	☐ Folio	☐ Outside Dimensions
		☐ Ovalized
		☐ Over/Under tolerance
		☐ Part Incorrect
		☐ Part Lost/Missing
		☐ Part Moved
		☐ Positioned Wrong
		☐ Power Loss/Surge
		☐ Pressure/Forced
		☐ Temperature/Cure
		☐ Weld
		☐ Wrong Stock Pulled
		☐ Other

Work Order ID 112983

Tuesday, February 11, 2014 11:31:59 AM

112983

Page 2

Item ID: PB67-43001-47

Revision ID:

Item Name: Base Assembly

Start Date: 2/11/2014 Start Qty: 6.00 *6*

Required Date: 2/28/2014 Req'd Qty: 6.00 *6*

Reference:

Accept

N900040100Setup Start ***NS1***Stop ***NS2***

Cust Item ID:

Customer:

Approvals: Process Plan: _____ Date: _____

QC: _____ Date: _____

Tooling: _____ Date: _____

SPC (Y/N): _____ Date: _____

Run Start ***NR1***Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

130

Identify as per dwg & Stock Location: 4

0.00

130

Packaging

Memo

MEZZA

0.00

Packaging

6 14.3.26 9-09
DAS 24

140

QC21- Final Inspection - Work Order Release

0.00

140

QC

Memo

0.00

Quality Control

MCS 14-03-26

MCS 14-03-26

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

DQA: _____ Date: _____

QA Closed: _____ Date: _____

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Work Order Update ☐	AGAINST DEPARTMENT/PROCESS <table style="width: 100%;"> <tr> <td>Skid-tube ☐</td> <td>Crosstube ☐</td> <td>Water Jet ☐</td> <td>Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>	Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐															
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐															
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐															
Large Fab ☐	Composite ☐	Supplier ☐																

Root Cause	Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Doc/Data									
Equip/Tooling									
Operator									
Material									
Setup									
Other									
Process									
Supplier									
Training									
Unapproved									

FAULT CATEGORY

Landing Gear ☐ Bending ☐ Centre Not Concentric to O/S ☐ Cracks ☐ Crushed/Crimped ☐ Cuffs ☐ Heat Treat ☐ Inspection Strip in Tube ☐ Ripples in Bend ☐ Torque Waves in Extrusion ☐ Turning Sequence ☐ Wave/Twist in Tube	General ☐ Bend ☐ BOM/Route ☐ Broken/Damaged ☐ Burrs ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Drill Holes ☐ Drawing ☐ Finish ☐ Folio	☐ Grain ☐ Hardware ☐ Inspection Incomplete ☐ Instructions Incomplete/Unclear ☐ Maintenance ☐ Mislabeled ☐ Misread ☐ Offset ☐ Out of Calibration ☐ Out of Sequence ☐ Outside Dimensions
		☐ Ovalized ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Positioned Wrong ☐ Power Loss/Surge
		☐ Pressure/Forced ☐ Temperature/Cure ☐ Weld ☐ Wrong Stock Pulled ☐ Other

Tuesday, February 11, 2014 11:31:56 AM

Required Qty: 6.00

IPP Rev C 10.09.28 per rev C

[illegible]

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

DQA: _____ Date: _____


QA Closed: _____ Date: _____

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Work Order Update ☐	AGAINST DEPARTMENT/PROCESS <table style="width: 100%;"> <tr> <td>Skid-tube ☐</td> <td>Crosstube ☐</td> <td>Water Jet ☐</td> <td>Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>	Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐															
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐															
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐															
Large Fab ☐	Composite ☐	Supplier ☐																

Root Cause	Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Doc/Data									
Equip/Tooling									
Operator									
Material									
Setup									
Other									
Process									
Supplier									
Training									
Unapproved									

FAULT CATEGORY


Landing Gear	General	Other
☐ Bending	☐ Bend	☐ Grain
☐ Centre Not Concentric to O/S	☐ BOM/Route	☐ Hardware
☐ Cracks	☐ Broken/Damaged	☐ Inspection Incomplete
☐ Crushed/Crimped.	☐ Burrs	☐ Instructions Incomplete/Unclear
☐ Cuffs	☐ Contamination	☐ Maintenance
☐ Heat Treat	☐ Countersink	☐ Mislabelled
☐ Inspection Strip in Tube	☐ Cut Too Short	☐ Misread
☐ Ripples in Bend	☐ Drill Holes	☐ Offset
☐ Torque Waves in Extrusion	☐ Drawing	☐ Out of Calibration
☐ Turning Sequence	☐ Finish	☐ Out of Sequence
☐ Wave/Twist in Tube	☐ Folio	☐ Outside Dimensions
		☐ Ovalized
		☐ Over/Under tolerance
		☐ Part Incorrect
		☐ Part Lost/Missing
		☐ Part Moved
		☐ Positioned Wrong
		☐ Power Loss/Surge
		☐ Pressure/Forced
		☐ Temperature/Cure
		☐ Weld
		☐ Wrong Stock Pulled
		☐ Other



B67-43001-47 BASE ASSEMBLY

- NOTES:
- 1) MATERIAL: NONE
 - 2) FINISH: NONE
 - 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
 - 4) UNITS: INCHES UNLESS OTHERWISE NOTED
 - 5) BREAK SHARP EDGES: N/A
 - 6) IDENTIFICATION: NONE
 - 7) WEIGHT: 3.68 lbs
 - 8) WELDING: PER QSI 004

ITEM	QTY	P/N	DESCRIPTION
1	X	B67-43001-47	BASE ASSEMBLY
3	1	B67-43001-139	SQUARE TUBE
4	2	B67-43001-141	SQUARE TUBE
5	2	B67-43001-143	SQUARE TUBE
6	3	B67-43001-315	HOOK
7	2	D3440-11	GUSSET



mk
112953
14-2-11.

RELEASED
2010-09-16

C	REDRAWN PREMIER AVIATION DRAWING IAW DART QSI 018 AND QSI 043. FOR PREVIOUS REVISIONS, REFER TO SHEET 15 OF PREMIER AVIATION DRAWING No. B67-43001. REASON: SEE PAR#09-011.		MB	09.06.10
REV.	DESCRIPTION		BY	DATE
DESIGN	RW	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA		
DRAWN				
CHECKED		DRAWING NO.	REV. C	
MFG. APPR.		B67-43001-47		SHEET 1 OF 1
APPROVED		TITLE	SCALE	
DE APPR.	N/A	BASE ASSEMBLY	NTS	
DATE	09.06.10	COPYRIGHT © 1995 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.		

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

DQA: _____ Date: _____

QA Closed: _____ Date: _____

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Work Order Update ☐	AGAINST DEPARTMENT/PROCESS <table style="width: 100%;"> <tr> <td>Skid-tube ☐</td> <td>Crosstube ☐</td> <td>Water Jet ☐</td> <td>Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>	Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐															
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐															
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐															
Large Fab ☐	Composite ☐	Supplier ☐																

Root Cause	Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Doc/Data ☐									
Equip/Tooling ☐									
Operator ☐									
Material ☐									
Setup ☐									
Other ☐									
Process ☐									
Supplier ☐									
Training ☐									
Unapproved ☐									

FAULT CATEGORY

Landing Gear ☐ Bending ☐ Centre Not Concentric to O/S ☐ Cracks ☐ Crushed/Crimped. ☐ Cuffs ☐ Heat Treat ☐ Inspection Strip in Tube ☐ Ripples in Bend ☐ Torque Waves in Extrusion ☐ Turning Sequence ☐ Wave/Twist in Tube	General ☐ Bend ☐ BOM/Route ☐ Broken/Damaged ☐ Burrs ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Drill Holes ☐ Drawing ☐ Finish ☐ Folio	☐ Grain ☐ Hardware ☐ Inspection Incomplete ☐ Instructions Incomplete/Unclear ☐ Maintenance ☐ Mislabeled ☐ Misread ☐ Offset ☐ Out of Calibration ☐ Out of Sequence ☐ Outside Dimensions
		☐ Ovalized ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Positioned Wrong ☐ Power Loss/Surge
		☐ Pressure/Forced ☐ Temperature/Cure ☐ Weld ☐ Wrong Stock Pulled ☐ Other